







INDUSTRY: POLYSTYRENE

CUSTOMER PROBLEMS.

The customer was having serious problems with monitoring a polystyrene process. There was no accurate means of measuring the size of the growing particles. Yield was bad due to waste in the process. None of the alternative instruments could adequately solve this problem.

CANTY'S SOLUTION.

Installing a Canty Vision / Lighting System, and a Canty Vector System with Particle Sizing software automates the entire process. Oversizing of particles can be avoided, therefore reducing wastage and optimizing yield. Also, the Canty Particle Sizing System provides a magnified view of the process to operators in the control room, which is invaluable to the customer.

EQUIPMENT.

Lighting / Vision System, Vector System with a 4-20mA output, and particle sizing software.

J.M. CANTY INC.

J.M. CANTY LTD.

Buffalo, NY USA Ph. (716) 625-4227 Fax. (716) 625-4228 98A7612 4-082400 Dublin, Ireland Ph. (353) (01) 459-8808 Fax. (353) (01) 462-5133

e-mail:sales@jmcanty.com
http://www.jmcanty.com/